

New PDL Firmware Revision 2.40

Pacific Crest Customer Support announces the release of PDL firmware 2.40.

Features/Enhancements for PDL 2.40

- Improved 4LFSK performance
- Improved compatibility with TRIMTALK 450S*

Upgrade Instructions

Upgrading PDL radios with the latest firmware is straightforward. Follow these steps to complete the upgrade:

1. Download the file called Pdl2p40.fw
2. Read the text file called ReadMe.TXT
3. Open PDLCONF.EXE
4. Connect PDL radio modem
5. Click on PCC file menu logo (upper left hand corner)
6. Select "Upgrade Modem Firmware"
7. Go to the location Pdl2p40.fw is stored and select it
8. Click Open to complete upgrade

Additional Information

File Name: Pdl2p40rel.fw

Release Date: May 2004

Applicable Products: PDLHPB, PDLRVR, PDLRTS, PDLLPB, PDLRXO, PDLEURO, EDL, EDL II

Software Requirements: PDLCONF revision 2.00 or higher

Availability: On the web at http://www.pacificcrest.com/tech_support/updates.shtml

Technical Support

The firmware is available for download from the web at www.pacificcrest.com on the downloads page. If you need assistance in the download or upgrade process, please contact our Technical Assistance Center at 1.800.795.1001 or via email at support@pacificcrest.com.

* TRIMTALK 450S is a registered trademark of Trimble Navigation Ltd.



990 Richard Avenue, Suite 110, Santa Clara, CA. 95050
Toll Free: 800.795.1001 Phone: 408.653.2070 Fax: 408.748.9984
Email: support@pacificcrest.com Web: www.pacificcrest.com