

December 17, 2001

New PDL Firmware Revision 2.10

Pacific Crest Customer Support announces the release of PDL firmware revision 2.10, which improves signal acquisition and co-channel radio performance in GMSK. We recommend that all products, both bases and rovers, be upgraded with this firmware.

The firmware is available for download from the web at www.paccrst.com on the Downloads page. If you need help in the download or upgrade process, please contact our Technical Assistance Center at 1-800-795-1001.

For additional information concerning Firmware Upgrades in PDL products, please contact **Pacific Crest Corporation** at 408-653-2070, 408-748-9984 (Fax), support@paccrst.com, or visit our web site at www.paccrst.com.

Marketing bulletins are published from time-to-time to keep OEMs, dealers and customers informed of important news. These bulletins contain information about new product releases, firmware and software upgrades, promotions, events, and other topics of interest. Marketing bulletins are designed to keep you informed, and are prepared for OEM, dealer and customer release. We encourage your feedback at all times concerning how we can improve our products and communications to serve you better.



PACIFIC CREST
CORPORATION

990 Richard Avenue, Suite 110
Santa Clara, CA. 95050
Toll Free: 800.795.1001

Phone: 408.653.2070 Fax: 408.748.9984

Email: Support@paccrst.com Web: www.paccrst.com